

AAON INC.

2425 S. YUKON AVE.
TULSA, OK 74107

SPA# SV05956-000-06

Ph. 918-583-2266
Fax 918-382-6369

GENERAL SPECIAL PRICING AUTHORIZATION

TO : WEB
COMPANY :
ORIGINATOR: RACHEL MARIE GRUNDMANN
FROM : PEYTON PATTERSON
JOBNAME :
ISSUE DATE: 2/14/2025

----- [SOI TEXT] -----

H3/V3/SB: FACTORY INSTALLED 100A NON-FUSED DISCONNECT
- WHIP CONNECTED TO UNIT WITH INTERNAL CONTROLS

REQUIREMENTS:

UNIT CANNOT BE CONFIGURED WITH EXTERNAL CONTROL BOX

----- [SPECIAL NOTES] -----

THIS SPA MAY BE ONLY APPLIED TO AN H3/V3/SB UNIT
CONFIGURED WITH INTERNAL CONTROLS (F15=0 OR D).

THE DISCONNECT WILL BE SHIPPED CONNECTED TO THE UNIT
BY LIQUID TIGHT CONDUIT, BUT IT WILL NOT BE MOUNTED
TO THE UNIT. DISCONNECT SWITCH MUST BE MOUNTED IN
THE FIELD.

IF AN EXTERNAL CONTROL BOX IS SELECTED, THIS SPA IS NOT
APPLICABLE.

A 36" CLEARANCE IS REQUIRED IN FRONT OF THE
DISCONNECT'S FINAL LOCATION.

UNIT MOP MUST BE LESS THAN OR EQUAL TO DISCONNECT SIZE.

TO ORDER A DISCONNECT FOR FIELD INSTALL, CONTACT THE
AAON PARTS DEPARTMENT AND ASK TO ORDER LONGVIEW PART
NUMBER 27897.

----- [DESCRIPTION] -----

H3/V3/SB: FACTORY INSTALLED 100A NON-FUSED DISCONNECT
- WHIP CONNECTED TO UNIT WITH INTERNAL CONTROLS

ACP # 27897

DISCONNECT WILL BE CONNECTED TO UNIT VIA A LENGTH OF 6
FOOT FLEXIBLE CONDUIT.

IF USED ON A H3/V3 CONDUIT WILL CONNECT TO THE
INTERNAL CONTROL PANEL IN THE AIR HANDLING UNIT.

AAON INC.

SPA# SV05956-000-06

2425 S. YUKON AVE.
TULSA, OK 74107

Ph. 918-583-2266
Fax 918-382-6369

GENERAL SPECIAL PRICING AUTHORIZATION

TO : WEB
COMPANY :
ORIGINATOR: RACHEL MARIE GRUNDMANN
FROM : PEYTON PATTERSON
JOBNAME :
ISSUE DATE: 2/14/2025

IF USED ON A SB CONDUIT WILL CONNECT TO THE MAIN POWER
CONNECTION LOCATION ON THE COMPRESSOR CABINET NEAR THE
CONTROL PANEL ACCESS DOOR.

Model	Required Features	List Price
GS-H3	NOT VALID W/ EXTERNAL CONTROL PANEL	\$7,269

The expiration date for this SPA is 1/31/2026

Failure to include this SPA with the Order Write UP may result in incorrect order entry.

AAON, Inc. reserves the right to void or change pricing without notice.