SPA# SV04099-000-04

2425 S. YUKON AVE. TULSA, OK 74107

Ph. 918-583-2266 Fax 918-382-6369

GENERAL SPECIAL PRICING AUTHORIZATION

TO :	WEB	
COMPANY : ORIGINATOR:	CP-BRIAN	
FROM :	PEYTON PATTERSON	
JOBNAME : ISSUE DATE:	2/14/2025	
	[SOI TEXT]	
H3/V3/M2 OPP CONFIGURED D	OSITE ACCESS SIDE COIL CONNECTIONS X COIL	
	[SPECIAL NOTES]	
UNIT HANDEDN SERVICE/FILT	ESS MUST BE SELECTED AS PRIMARY ER ACCESS.	
	BE APPLIED TO ANY H3/V3/M2 CABINET SIZE. ONLY INTENDED FOR USE WITH DX SPLIT	
SERVICE CLEA	RANCE IS REQUIRED ON THE SIDE OPPOSITE	
- FOR H3/V3 CONFIGURED - FOR M2 UN	UNITS THE COIL SERVICE ACCESS IS ON THE ACCESS SIDE. ITS THE COIL SERVICE ACCESS IS ON THE	
OPPOSITE AC	CESS SIDE ALONG WITH THE COIL CONNECTIONS.	
	NNECTION SHALL EXIT THE UNIT ON THE ACCESS SIDE.	
	[DESCRIPTION]	
	OSITE HAND CONNECTIONS IONS, W/ DX COIL	
SECTION WHER	NECTIONS IN THE MAIN COIL SECTION OR M2 E THE SPA IS APPLIED WILL EXIT THE UNIT CONFIGURED ACCESS SIDE.	
OPPOSITE CON	PANEL SHALL BE INSTALLED ON THE SIDE FIGURED HANDEDNESS TO ALLOW SERVICE THE EXPANSION VALVES.	
	RAIN CONNECTION REMAINS ON IGURED ACCESS SIDE.	
SEE PRODUCT	MANAGER FOR COIL SPECIFICATION.	
Model	Required Features	List Price

AAON INC.

SPA# SV04099-000-04

2425 S. YUKON AVE. PTULSA, OK 74107 F

Ph. 918-583-2266 Fax 918-382-6369

GENERAL SPECIAL PRICING AUTHORIZATION

TO : WEB

COMPANY :

ORIGINATOR: CP-BRIAN

FROM : PEYTON PATTERSON

JOBNAME :

ISSUE DATE: 2/14/2025

| GS-ALL | FEATURE23=X | \$3,000 |

The expiration date for this SPA is 1/31/2026

Failure to include this SPA with the Order Write UP may result in incorrect order entry.

AAON, Inc. reserves the right to void or change pricing without notice.